

1/7




Fig. 1A Fig. 1B Fig. 1C Fig. 1D

2/7 -101 -110 -101 -110 -110 110 -112 122 114 -112 -120 -112 -112 400 120 -120 420 420 420 - 130 -400 - 130 130 - 130 400 400 Fig. 1G 1E 1F Fig. Fig.

3/7

 \neg




Fig. 2A


 $ldsymbol{f L}$


Fig. 2B

Thru Tubing Tool and Method Inventor(s): John E. Campbell, et al. Serial No. 10/719,199

Replacement Sheet


4/7





L

5/7




Thru Tubing Tool and Method Inventor(s): John E. Ĉampbell, et al. Serial No. 10/719,199

Replacement Sheet

6/7



 $ldsymbol{f L}$








Fig. 7

Fig. 8

Fig. 10




Fig. 11

 \mathbb{L}

Fig. 12

Fig. 13